RADIO COMMUNICATIONS



Bi-Directional Amplifier (BDA) Solutions

Reliable Two-Way Emergency Radio Communication



Emergency Responders lose communications when radio signals in-building are weakened by structures such as concrete, windows, and metal. Staying informed with clear radio transmissions between first responders inside of a building and emergency personnel outside of the building can help prevent injuries and save lives.

NOTIFIER's Bi-Directional Amplifier (BDA) System is a signal boosting solution designed to enhance in-building radio frequency (RF) signal coverage for public safety radio. When combined with industry leading fire systems, NOTIFIER provides the reliability and quality expected from a life safety solution.

Reliable Performance

Specifically designed to meet UL2524 In-building 2-Way Emergency Radio Communication Enhancement Systems, NOTIFIER's Class B, Bi-Directional Amplifier Solutions provide a high power, band-selective radio signal booster system that can be designed and customized to meet all public safety frequency band ranges. This state of the art BDA System is developed to provide a high rejection of interfering signals, and is designed for excellent heat dissipation, corrosion resistance and ease of wall-mounting.

Features and Benefits

- UL2524 for In-building 2-Way Emergency Radio Communication Enhancement Systems listing, CSFM listing
- NFPA 72 2010 Edition, NFPA 1221 2016 Edition and IFC 2018 compliant
- Supports all US public safety frequency bands
- Directly integrates with NOTIFIER Fire Alarm Control Panel
- Single BDA to cover multiple sub-bands with a wider bandpass
- Automatic and self adjusting oscillation prevention and uplink squelch support
- Lower power consumption for long term reliability and efficiency






RADIO COMMUNICATIONS

IS YOUR BUILDING IN THE EMERGENCY **COMMUNICATIONS DEAD ZONE?**

First Responders depend on reliable two-way communications when lives and property are at risk.







FIRST RESPONDER COMMUNICATION ISSUES



reported building

dead spots

Source: International


Assoc. of Fire Chiefs Survey | December 2017 experienced in-building


communications failure in emergencies (in the last 2 years)



experienced communications failure (in the last 6 months)

100% RELIABLE COMMUNICATION





NOTIFIER

12 Clintonville Road Northford CT 06472 203.484.7161 www.notifier.com



433 Industrial Drive North Wales, PA 19454 (888) 641-0100 www.keystonefire.com EIN #23-2019550

